


Item	Qty.	Description
1	1	23" w x 38" h LT Panel
2	1	38" h LT 90° Corner Connector
3	1	14.125" w x 38" h LT Panel
4	1	38" h LT 90° Corner Connector
5	1	23" w x 38" h LT Panel w/ Door
6	1	38" h LT 90° Corner Connector
7	1	14.125" w x 38" h LT Panel
8	1	38" h LT 90° Corner Connector
1,1A	1,1	35" S44 Vertical Extrusion

Steps:

Refer to the LT Panel Assembly general information page.

- 1) Assemble panels & connectors [1] through [10] in numerical order as shown.
- 2) Connect verticals [1-1A] together. See S44 Connection detail.
- 3) Attach vertical assembly [1/1A] to panel [5] using screw caps.
- 4) Affix Shelf Supports to inside of counter assembly; place Shelf onto supports.
- 5) Slide Counter Top over vertical assembly [1/1A] & secure to top of counter assembly. See Counter Top Attachment detail.
- 6) Install Monitor Mount to vertical [1/1A]. See Monitor Mount Attachment detail.

When assembled






*** Monitor Mount Attachment**

Slide V4 Connectors into groove of Extrusion. Tighten Set Screws to secure connectors in place.

Attach Monitor Mount back piece to Extrusion, using bolts.

Then slide monitor mount into back piece.



*** S44 Connection**

Connector

Screws

Slide extrusion over connector and rest on lower vertical; secure with screws.

****To prevent product loss, Keep all screws attached to connector piece after disassembling**

*** Counter Top Attachment**

1 Align hole with pin.

2 Rotate pin. Spring will push pin into hole.

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts: Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. **Heat and UV exposure will warp and fade components.**
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly


- For loss prevention, tighten all set screws and locks during disassembly.




Hex Tool - Essential for Assembly




Part Identification - Numbering




Spline Connection



Base Plate & Extrusion Connection



Extrusion & Lock Connection



Engaged Lock



WARNING



DO NOT USE POWER TOOLS



LADDERS OR LIFTS
MAY BE REQUIRED



ALL CONNECTIONS MUST
BE TIGHTLY SECURED